

Transaction Information

Tool ID	32A4MA
Tool Status	Disconnected
Location	Burlington, USA
Wafer Size	200 mm
Fab Section	Support Tools
Tool Available Date	2024-07-24

General Product Information

Vendor Supplier	Rudolph
Model	ws-3000hs
Vintage	2003
Serial No	ws-3008
Asset Description	Non working/running rvsd inspection set up for 267mm TSV. Missing robot, ocr cameras
Software Version	does not fire up
CIM	none
Process	Running 267mm TSV only

Hardware Configuration (Fab)

System Type	Description	Quantity	Status
Main System	tsv inspection	1	OK
Handler System	stand off tsv loader	1	OK
Factory Interface	Open Cassette	1	OK
Options System			

Hardware Configuration (Subfab / Auxilliary Units)

Description	Quantity	Status
ws-3000		

Missing/Faulty Parts / Accesories List

Description	Quantity
robot,loadports (load/unload)	1

Tool Pictures

General

rvsi 267 tsv Inspection tool



Hardware Sub-fab

inside tool




Manufacture Serial

TAG




Missing Parts

missing robot/ocr camera



Missing Parts

missing robot/ocr camera



Additional Tool Data Files